

46.105 Contractor responsibilities.

(b) The contractor is required to maintain calibrated measuring and test equipment used for test and verification of products offered. The product specialist shall insert the TQ STO RT001 Measuring and Test Equipment in the PID.

Parent topic: [SUBPART 46.1 – GENERAL](#)